



LIST OF DRAWINGS

NO.	TITLE
1	GENERAL ARRANGEMENT
2	YOKE
3	STAND, CAPS, ETC.
4	COLUMN
5	BRACE
6	BASE
7	CONE PULLEYS
8	PULLEYS, SHAFT
9	COUPLING, SHAFT
11224	TABLE
11228	COLLAR FOR SPINDLE
11228	SLEEVE FOR SPINDLE
11229	BALL RACE
11240	FEED PINION
11261	COLLAR FOR PINION SHAFT
11278	SCREW FOR FORK
11280	HANDLE FOR SCREW
11284	LOCK WASHER
11287	SPINDLE
11281	SPRING FOR COLLAR
11282	SPRING FOR PINION
11283	FRICTION COLLAR

LIST OF PATTERNS

PATT. NO.	NAME	DRAWING NO.
01	YOKE	2
02	BEARING STAND	3
03	CAP	3
04	CAP	3
05	COLUMN	4
06	BRACE	5
07	BASE	6
08	UPPER CONE PULLEY	7
09	LOWER CONE PULLEY	7
10	PULLEY	8
11	PULLEY	8
12	PULLEY	8
13	COLLAR	8
14	BUSHING	8
15	PULLEY	8
16-A	COUPLING	9
16-B	COUPLING	9
11224	TABLE	11224
11228	SLEEVE FOR SPINDLE	11228

SPINDLE: SP1125 - 400, 433, 965, 1410

UNIVERSITY OF KENTUCKY - LEXINGTON
10" DRILL
GENERAL ARRANGEMENT

REVISED JAN 1955
SECTION A-A ADDED - MOTOR CHANGED
DRAWING NO. 1 JUNE 24 1954 SCALE 3/4" = 1"