

*Wis Steel Co  
Benham Ky*

*Engine*



January 3, 1919. 9890

Mr. C. R. McDonald,  
Purchasing Department.

Dear Sir:

WISCONSIN STEEL COMPANY - BENHAM  
DEFECTIVE GOVERNOR DASH POT

You may say to Mr. Hickok and to the Rdigway Dynamo & Engine Company that I have heard no further complaint on the working of the governor dash pot since the new one was put on and the one with the little blow holes in it taken off.

You may further say that I was present personally when the defective dash pot was taken off and examined by our master mechanic, machine shop foreman and electrician and that we were able to squeeze oil through the blow holes in the casting and in order to run as we had to we filled the holes with solder as best we could and when that was done the engine held better and governed more nearly as it would be expected to do. These are the facts in this case. The dash pot was defective and put us to much trouble and inconvenience in our operations. Their men better look out for those "little spots" and blow holes in essential castings for such important service. We do not see that there is any argument on this matter so far as we are concerned at all. They supplied us with a defective governor dash pot and have now supplied us with a proper one to take its place under guarantee to replace defective parts.

Attached find copies of telegrams that explain themselves.

Very truly yours,

(Enclosure)

F L STEVENSON D